

www.phantom-windsurfing.com



User Manual Iris R, X, Z Foil 2021/2022

# **COMMON SET**


### For the 800, 950 and 1000 Front Wings

## TOOLS:




\*Corrosion settles mainly in the zones where carbon and aluminum are in contact.

### Parts:







## SPECIAL SET


#### For the 350,430, 550 and 730 Front Wings

## TOOLS:




\*Corrosion settles mainly in the zones where carbon and aluminum are in contact.


### Parts:



### **EXPLODED:**



#### MAST SETUP:




The fuselage angle should be 3 ° greater than the parallel between the bottom of the cassette and the fuselage to get the perfect axis.

Use the Shims for your setup.

# Setting shims box by Nico GOYARD: includes





#### STAB SETUP:

All windsurfing gear and windsurfer levels are different. It is possible to adjust the flying power of your foil according to your feeling.

The standard setup without any shim is the max power you can get for large sails and heavy sailors.
We recommand the use of shims to reduce the power.

Please find a small plastic sachet containing shims to adjust the stab.

- Fuselage 90 cm & 110 cm Standard Trimming



- Fuselage 90 cm

Trim with the shims to limit the flight power



- Fuselage 110 cm

Trim with the shims to limit the flight power

